


COSHH ASSESSMENT

PRODUCT NAME:	White Grease	MANUFACTURER:	Sealey
DATE	24/07/2025	STORAGE LOCATION:	Metal Cabinet
PROCESS:	Spray onto area		

CLASSIFICATION OF SUBSTANCES

								
Explosive	Flammable	Gas under pressure	Oxidising	Corrosive	Acute Toxicity	Hazardous to environment	Health Hazard	Health Hazard
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

CONTROL MEASURES FOR SAFE USE:

Control Measures

Keep away from heat, sparks and open flame. Avoid spilling, skin and eye contact. Ventilate well, avoid breathing vapours. Use approved respirator if air contamination is above accepted level.

Storage

Aerosol cans: Must not be exposed to direct sunlight or temperatures above 50°C

SIDE EFFECTS

Symptoms

No data available.

EXPOSURE LIMITS

Yes

See "Occupational exposure limits" for more details.

PROTECTIVE CLOTHING OR EQUIPMENT (IF ANY) NECESSARY DURING USE:

	Safety Boots		Yes		
	Safety Goggles				
				OTHER	

COSHH ASSESSMENT

THE SUBSTANCE IS HAZARDOUS TO HEALTH WHEN:

In contact with Skin



In contact with Eyes



Breathed in



Swallowed



PRODUCT TYPE

Gas



Vapour



Mist



Fume



Dust



Liquid



Solid



FIRST AID – ACTION TO BE TAKEN IF SUBSTANCE IS:

Swallowed	DO NOT INDUCE VOMITING! Rinse mouth thoroughly with water and give large amounts of milk or water to people not unconscious. Get medical attention if any discomfort continues.	In Contact with Skin	Wash the skin immediately with soap and water. Get medical attention if any discomfort continues.
Inhaled	Move the exposed person to fresh air at once. When breathing is difficult, properly trained personnel may assist affected person by administering oxygen. Keep the affected person warm and at rest. Get prompt medical attention.	In Contact with Eyes	Make sure to remove any contact lenses from the eyes before rinsing. Promptly wash eyes with plenty of water while lifting the eye lids. Continue to rinse for at least 15 minutes. Get medical attention if any discomfort continues.

FIRE PRECAUTIONS:

Extinguishing Media	Powder. Dry chemicals, sand, dolomite etc. Water spray, fog or mist.	Hazardous combustion products	None Listed
Unsuitable extinguishing Media	None Listed	Advice for fire-fighters	Containers close to fire should be removed or cooled with water. Use water to keep fire exposed containers cool and disperse vapours.

CHEMICAL REACTIONS:

Conditions to avoid Avoid heat, flames and other sources of ignition. Avoid contact with: Strong oxidising agents. Strong alkalis. Strong mineral acids.

Materials to avoid. No information available.

Hazardous decomposition products : Vapours/gases/fumes of: Carbon monoxide (CO). Carbon dioxide (CO₂)

ACCIDENTAL RELEASE MEASURES:

No data available.

DISPOSAL OF THIS PRODUCT

Wear necessary protective equipment. Extinguish all ignition sources. Avoid sparks, flames, heat and smoking. Ventilate. Let evaporate. Keep out of confined spaces because of explosion risk. If leakage cannot be stopped, evacuate area.

OCCUPATIONAL EXPOSURE LIMITS

ASSESSOR NAME: